# **Mid-Summer 2024 Construction Update**







### Information included



- Project Updates
- Project Schedules
- Progress Photos



**Elk Grove –** Student Services (March – August)

- Drywall completion
- Painting in Progress
- Ceiling grid installation underway
- Interior Finishes
- Above-ceiling mechanical finishes
- Installation of light fixtures

- Work on bathroom tile
- Installation of carpet throughout
- Career Center
- Completion of logo installation
- Progress on finishing work in this area



**Elk Grove –** Culinary Classroom (June – September)

- Demolition is completed.
- Underground gas, electrical and plumbing connection are almost done.
- Layout of the rooftop equipment is completed with the steel reinforcing.



**Prospect –** Roof Replacement (June – August)

- All roof demolition has been finished.
- All existing rooftop equipment and exhaust fans have been removed.
- New curbs and equipment have been installed.
- We are working on making the final connections to the new equipment and plan to start by the end of July.
- The rooftop insulation has been delivered to the site, and the contractor began work on isolation.



**Prospect –** Pool Basin Plaster Replacement (June – August)

- Demo of the existing plaster completed
- Hydroblasting completed
- The contractor is cleaning the basen
- Tile repair and replacement will start this week
- Plastering the pool




### **Buffalo Grove –** Athletic Fields Phase 1 (June – November)

- Temporary fencing has been installed on the site.
- Demolition is completed.
- The team received the MWRD permit on 6/11/24, allowing the rest of the construction to begin.
- SWPPP provisions have been installed on the site, and site clearing is finished.
- We are currently working on mass-site grading on the north shelf.
- Site utilities are in progress, and the structures for the lift station in the plaza by the field house have been set.
- We are preparing to lay out the foundations and footings by the end of the month.



**Buffalo Grove –** Boiler Replacement (June – September)

- The doorway into the mechanical room has been opened up to accommodate the transfer of large equipment.
- The (10) existing boilers have been removed, and all associated piping has been hauled away.
- The (4) new boilers are in position and new piping to them is underway.
- Flues and combustion air intakes are already installed up through the roof surface.
- Primary Supply and Return header piping has been installed.
- The (4) Pump VFDs have been replaced.







Elk Grove High School – Student Services




Elk Grove High School – Student Services



Elk Grove High School – Student Services



Elk Grove High School – Culinary Classroom




Elk Grove High School – Culinary Classroom




Prospect High School – Roof Replacement



Prospect High School – Roof Replacement




Prospect High School - Roof Replacement



Prospect High School – Pool Plaster Replacement



Prospect High School – Pool Plaster Replacement



Buffalo Grove High School – Ballfield Replacement Phase 1



Buffalo Grove High School – Ballfield Replacement Phase 1



Buffalo Grove High School – Ballfield Replacement Phase 1



Buffalo Grove High School – Boiler Replacement



Buffalo Grove High School – Boiler Replacement